

# Annexure D

## BUILDING SAFETY CERTIFICATE

No.

Dated:

It is certified that the existing building **Meena Shah Public School, Circular Road, Near Karbala, Gonda (U.P)** (name and address of the building or premises) is having block(s)/Floor(s) as per details below:

Details Of Block in School	Block (1)
No. of Floors in the Block	G+1

The building is owned/occupied by building **Meena Shah Public School, Circular Road, Near Karbala, Gonda (U.P)** (name and address of the Institution) have complied with the Building safety requirements in accordance with National Building Code Rules, and verified by the officers concerned of .....(Name of Department/ Govt.) on.....(date of inspection) in the presence of **Mr. Saeed Hasan, Manager, Meena Shah Public School, Circular Road, Near Karbala, Gonda (U.P)** (name and addresses of the Manager/ Secretary or his representatives) and that the building/premises is fit for occupancy for running school with effect from ..... for a period of 02 years in accordance with rule and subject to compliance of the specific conditions as appended.

1. School building is designed according to National Building Code 2005 standards.
2. The school building is earthquake resistant.
3. The school building is built according to the plan.

Issued on ..... at Gonda, by Executive Engineer (R.E.D.), Gonda, U.P.



Signature with Seal: \_\_\_\_\_

Name: \_\_\_\_\_

Designation: \_\_\_\_\_

Name & Address of Department/ Office: \_\_\_\_\_